

# Oil Field Environmental Incident Summary

**Incident:** 20140502155334      **Date/Time of Notice:** 05/02/2014 15:53

**Responsible Party:** ENDURO OPERATING, LLC

**Well Operator:** ENDURO OPERATING, LLC

**Well Name:** 20401 JV-P OLSON 1313

**Field Name:** STONEVIEW

**Well File #:** 13065

**Date Incident:** 5/2/2014      **Time Incident:** 11:30

**Facility ID Number:**

**County:** DIVIDE

**Twp:** 160

**Rng:** 95

**Sec:** 13

**Qtr:** SW SW

**Location Description:**

**Submitted By:** Scott Hunskor

**Received By:**

**Contact Person:** Scott Hunskor  
777 MAIN STREET  
SUITE 800  
FORT WORTH, TX 76102

**General Land Use:** Cultivated

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:** 1 Mile

**Distance Nearest Water Well:**

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained in Dike:** No

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	1	Barrels	1	Barrels	1	barrels
Brine						
Other	20	Barrels	15	Barrels	15	barrels

**Description of Other Released Contaminant:**

Fresh Water

**Inspected:**

**Written Report Received:** 10/6/2015

**Clean Up Concluded:** 5/6/2014

**Risk Evaluation:**

none

**Areal Extent:**

5' x 10' mostly on location but did connect with edge of cultivated field.

**Potential Environmental Impacts:**

none

**Action Taken or Planned:**

Shut down pressure testing, called in vac truck to pick up pooled water, will scrape oil skim off and haul away

**Wastes Disposal Location:** Into barrels to be hauled to an approved disposal facility

**Agencies Involved:**

**Updates**

---

**Date:** 5/4/2014      **Status:** Reviewed - Follow-up Required

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release from an on-location valve/piping leak partially impacted a cultivated farm field. Report indicates fresh water and 1 bbl of oil. Followup is necessary.

---

**Date:** 5/8/2014      **Status:** Inspection

**Author:** Martin, Russell

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

5/8/2014 at 17:13, on location. Impact to vegetation visible at NW corner of pad. ~10x10 foot spot right next to the well pad that shows impact, as well as another 10-ft by 1-ft leg where it appears the fresh water pushed some residue. Along north side of pad near dismantled heater treater, I noted a discolored spot with dead vegetation in a 2x3 foot spot. Notified report contact of findings; depending on the weather, it will be cleaned up sometime next week. Plan is to scrape up the impacted soil and vegetation.

---

**Date:** 7/3/2014    **Status:** Correspondence

**Author:** Martin, Russell

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Phone call with report contact. According to contact, cleanup is complete.

---

**Date:** 7/8/2014    **Status:** Inspection

**Author:** Martin, Russell

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

7/8/2014 at 11:15, on location. Off-pad location to NW appears clean; no visible staining to vegetation off location in this area. Area next to pad in this area has been scraped. Some staining is visible around pad, and some vegetation that is growing within the pad area is stained. Small stain off northside of wellpad still evident in vegetation.

---

**Date:** 9/17/2014    **Status:** Inspection

**Author:** Martin, Russell

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

9/17/2014 at ~16:20, on location. Met with Enduro personnel and pointed out spots that need further cleanup. Personnel will be having a crew clean up the site, remove old leaking equipment and tidy up the wellpad.